

148mm

210mm

anko

Digital Travel Scales

Instruction Manual

K: 43-653-515 | T: 71-888-576


To make sure to use this scale correctly and keep long life of scale, please read this manual carefully.

FEATURES:

- Max weight capacity: 50kg
- Min weight capacity: 0.05kg
- Division value: 0.01kg
- Units: kg, g, lb, oz
- Automatic switch off after 30 seconds.
- Product weight: 85g (batteries not included)

INSERTING THE BATTERIES

1. Remove the battery compartment cover and insert 2 x 1.5V AAA batteries (included). Ensure batteries are inserted with correct polarity. Do not mix old and new batteries. Do not mix different types of batteries (alkaline, carbon zinc, rechargeable).
2. Replace the battery compartment cover again.



POWER ON

Hand hold the scale level, press ON/TARE button, the screen will display HELLO then 0g about 2 seconds later, now the scale is ready to weigh.

TARE or ZERO

Load a container and lift up the scale, you will see the container weight, press ON/TARE button, the scale will display 0g, load something you want to weigh then screen will display the net weight.

AUTO LOCK

This scale has auto lock or hold function. When weighing, once the reading is stable, the scale will auto lock the data and HOLD will be displayed on screen. To unhold, please press ON/TARE one time.

WEIGHING

Power on and load something when the scale is ready to weigh, the weight will be displayed on screen. Once the weighed item stop swaying, the reading will be stable then be auto locked. If overload, the scale will display Hold and warning alarm will work.

UNIT SWITCH

Press UNIT button, g/lb/oz/kg will switch circularly.

PRESET ALARM OF TARGET WEIGHT

You can preset a target weight, if overload the target weight, the scale display light will change from blue color to red color.

To preset a target weight, power on then press and hold the UNIT button, and at the same time, double-click the ON button quickly, now you can preset a target weight from 1kg to 50kg. Press UNIT button one time to increase 1kg, press ON button one time to decrease 1kg, or long press UNIT/ON button to change the target weight quickly. Once the target weight is selected, the scale will auto restart 3 seconds later then set up is done.

POWER OFF

- * The scale will auto power off 30 seconds later if no operation.
- * Manual power off. Can not power off if the scale is weighing. Press ON/TARE to unlock first if the scale is holding a weight then long press ON/TARE again to power off. If the scale is not in HOLD status, long press ON/TARE to power off directly.

INDICATORS

When power off. Will beep once when a weight is locked.

TO REPLACE BATTERIES

If the scale batteries need to be replaced, lift the compartment of the battery cover on the bottom of the scale and replace the old batteries with 2 x 1.5V Alkaline (AAA) batteries.

WARNINGS

Insert batteries with the correct polarity and always follow the manufacturer's instructions. Do not mix new and used batteries or alkaline, standard (carbon-zinc), or rechargeable (nickel-cadmium) batteries. Remove batteries if product will be stored for an extended period. Dispose of used batteries responsibly.

MADE IN CHINA

CUSTOMER SERVICE:
KMART AU: 1800 124 125
KMART NZ: 0800 945 995
TARGET AU: 1300 753 567